

Inspection Type COMPLIANCEInventory No. 4650Inspection Frequency QUARTERLY

Authorization \_\_\_\_\_

Violation Code H-2

Authorized to Inject \_\_\_\_\_

Company/Operator SANTA FE MINERALS % KWBBusiness Address 3300 FIRST NATIONAL TWR.TULSA, OK.74103Individual Contacted NONE

Title \_\_\_\_\_

Lease Name & Well No. AVANT #4Legal Description (b) (9)Well Information: SWD/ER Active/TA/P&AAuthorized Injection: Pressure NA.Rate NA.Long String Casing Size 6 5/8Tubing Size NONE

## Report of Conditions as of this Date:

Lease: Active/InactiveWell hooked up for injection: Yes/NoInjecting at time of inspection: Yes/NoRequired fittings on tubing and casing/tubing annulus: Yes/~~No~~/Not ApplicableInjection Pressure N.A.; How Determined P&AAnnular Pressure N.A.; How Determined \_\_\_\_\_Injection Rate 0; How Determined \_\_\_\_\_Well plugged at Surface: Yes/No/UndeterminedSamples Taken NOPhotographs Taken NO

Description of wellhead hookup and injection facility:

WELL IS PLUGGED & ABANDONED.

RECEIVED

OCT 7 1988

EPA GW-S

REGION VI

Weather Conditions and Observations Partly cloudy, cool & dry.FRESH CEMENT ON LOCATION. LOCATION RESTOREDInspection Date 10-4-88Time Arrived 11:20Departed 11:35Field Inspector MARK HENDRICKS

EPA Reviewer \_\_\_\_\_

Date \_\_\_\_\_